


# SAFETY GAS DETECTION

## SERVICE RECORD

Using Technology to Safeguard Life

| <b>Customer</b>   | North Lanarkshire Council           | <b>Postcode</b>          | ML2 2HT Townhead Rd  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
|---|-------------------------------------|--------------------------|--|--|-----|------|----------|-----|--|-------------------|-----------|---|--|---------|--|---|--|--------------------|--|---|--|--------------|-----------|---|
| <b>Building</b>   | Main School Building                | <b>Room</b>              | Janitors Office  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Contact</b>  | Ellen Douglas (Head) / Helen Taylor |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Manufacturer</b>   | SGD                                 | <b>S/N</b>               | 120203-002   |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Sys Description</b>  | Intelligent Fan Control System      |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Notes</b>  | Normal Panel Key.                   |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Gas Measured</b>   | CH4%                                | CO2%                     |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>1st Alarm Level</b>  | 1.0                                 | 1.0                      |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>2nd Alarm Level</b>  | 2.5                                 | 2.5                      |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>3rd Alarm Level</b>  |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>4th Alarm Level</b>  |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| Task:<br>Changed Sensors #: CO2<br>Calibration                                      |                                     |                          | <b>Sensor List:</b><br><table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">No.</th> <th style="width: 20%;">Type</th> <th style="width: 20%;">Date Due</th> <th style="width: 5%;">Qty</th> </tr> </thead> <tbody> <tr> <td></td> <td>Pump, Double Head</td> <td>23-May-19</td> <td>1</td> </tr> <tr> <td></td> <td>CO2-Dyn</td> <td></td> <td>1</td> </tr> <tr> <td></td> <td>CH4-Dyn<br/>CH4-Dyn</td> <td></td> <td>1</td> </tr> <tr> <td></td> <td>Filter, Bowl</td> <td>23-May-19</td> <td>1</td> </tr> </tbody> </table> NSD23/05/2019 |  | No. | Type | Date Due | Qty |  | Pump, Double Head | 23-May-19 | 1 |  | CO2-Dyn |  | 1 |  | CH4-Dyn<br>CH4-Dyn |  | 1 |  | Filter, Bowl | 23-May-19 | 1 |
| No.   | Type                                | Date Due                 | Qty  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
|   | Pump, Double Head                   | 23-May-19                | 1  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
|   | CO2-Dyn                             |                          | 1  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
|   | CH4-Dyn<br>CH4-Dyn                  |                          | 1  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
|   | Filter, Bowl                        | 23-May-19                | 1  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| Test Gas:<br>#1028 : 2% CO2 / 2% H2 / 15% O2 / Bal N2                               |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| Notes:<br>Changed 2% CO2 sensor to 5% CO2 sensor.                                   |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Result: Pass</b>   |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| Remedial Required? No   |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Completed By:</b>  |                                     |                          | <b>Name:</b>   |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| Liam Colbert  |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Signature:</b>   |                                     |                          | <b>Signature:</b>  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
|  |                                     |                          |  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| <b>Next Visit Due:</b>  |                                     | <b>Service Interval:</b> | <b>Date:</b>   |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |
| 10-May-19   |                                     | 6                        | 07-Nov-18  |  |     |      |          |     |  |                   |           |   |  |         |  |   |  |                    |  |   |  |              |           |   |

For Office Use Only: St. Ambrose Glasgow North Lanarkshire School

01-May-19

Send To: Gerry Boyle boyleg@northlan.gov.uk