


SAFETY GAS DETECTION

SERVICE RECORD

Using Technology to Safeguard Life

Customer	North Lanarkshire Counsel	Postcode	ML2 2HT Townhead Rd																					
Building	Main School Building	Room	Janitors Office																					
Contact	Ellen Douglas (Head) / Helen Taylor																							
Manufacturer	SGD	S/N	120203-002																					
Sys Description	Intelligent Fan Control System																							
Notes																								
Gas Measured	CH4%	CO2%																						
1st Alarm Level	1.0	1.0																						
2nd Alarm Level	2.5	2.5																						
3rd Alarm Level																								
4th Alarm Level																								
Task: Calibration Changed Sensors #: Functional Test of Sensors Functional Test of Fans Serviced				Sensor List:																				
				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">No.</th> <th style="width: 40%;">Type</th> <th style="width: 20%;">Date Due</th> <th style="width: 10%;">Qty</th> </tr> </thead> <tbody> <tr> <td> </td> <td>Pump, Double Head</td> <td>04-May-18</td> <td>1</td> </tr> <tr> <td> </td> <td>CO2-Dyn</td> <td> </td> <td>1</td> </tr> <tr> <td> </td> <td>CH4-Dyn CH4-Dyn</td> <td> </td> <td>1</td> </tr> <tr> <td> </td> <td>Filter, Bowl</td> <td>04-May-18</td> <td>1</td> </tr> </tbody> </table>	No.	Type	Date Due	Qty		Pump, Double Head	04-May-18	1		CO2-Dyn		1		CH4-Dyn CH4-Dyn		1		Filter, Bowl	04-May-18	1
				No.	Type	Date Due	Qty																	
					Pump, Double Head	04-May-18	1																	
					CO2-Dyn		1																	
	CH4-Dyn CH4-Dyn		1																					
	Filter, Bowl	04-May-18	1																					
NSD04/05/2018																								
Test Gas: #1024 : 250ppm CO / 2% CO2 / 2.5% CH4 / 15% O2 / Bal N2																								
Notes: Changed CH4 sensor. Adjusted zero & span of CH4 sensor within Software. Cleaned all fan panel & main control panel filters. Re-set maintainance timer & tested fault input/output - LC																								
Result: Pass																								
Remedial Required? No																								
Completed By:			Name:																					
Liam Colbert																								
Signature:			Signature:																					
																								
Next Visit Due:		Service Interval:	Date:																					
09-May-18		6	09-Nov-17																					

For Office Use Only: St. Ambrose Glasgow North Lanark.. (Was Landline)

01-Apr-18

Send To: Gerry Boyle boyleg@northlan.gov.uk