


# SAFETY GAS DETECTION

## SERVICE RECORD

Using Technology to Safeguard Life

<b>Customer</b>	Was Landline	<b>Postcode</b>	ML2 2HT Townhead Rd																	
<b>Building</b>	Main School Building	<b>Room</b>	Janitors Office																	
<b>Contact</b>	Ellen Douglas (Head) / Helen Taylor																			
<b>Manufacturer</b>	SGD	<b>S/N</b>	120203-002																	
<b>Sys Description</b>	Intelligent Fan Control System																			
<b>Notes</b>																				
<b>Gas Measured</b>	CH4%	CO2%																		
<b>1st Alarm Level</b>	1.0	1.0																		
<b>2nd Alarm Level</b>	2.5	2.5																		
<b>3rd Alarm Level</b>																				
<b>4th Alarm Level</b>																				
<b>Task:</b> Calibration Changed Pump #: Double Head Pump Changed Filter #: In Line Sampling Filter Functional Test				<b>Sensor List:</b>																
				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">No.</th> <th style="width: 40%;">Type</th> <th style="width: 20%;">Date Due</th> <th style="width: 10%;">Qty</th> </tr> </thead> <tbody> <tr> <td> </td> <td>Pump, Double Head</td> <td>04-May-18</td> <td>1</td> </tr> <tr> <td> </td> <td>CO2-Dyn</td> <td> </td> <td>1</td> </tr> <tr> <td> </td> <td>CH4-Dyn CH4-Dyn</td> <td> </td> <td>1</td> </tr> </tbody> </table>	No.	Type	Date Due	Qty		Pump, Double Head	04-May-18	1		CO2-Dyn		1		CH4-Dyn CH4-Dyn		1
				No.	Type	Date Due	Qty													
					Pump, Double Head	04-May-18	1													
					CO2-Dyn		1													
	CH4-Dyn CH4-Dyn		1																	
NSD04/05/2018																				
<b>Test Gas:</b> #984 : 1.85% CO2 / 15% O2 / 2%H2 / Bal N2 #1014 : 1.85% CO2 / 2% CH4 / 250ppm CO / 15% O2 / Bal N2																				
<b>Notes:</b> Serviced, changed double head pump. Cleaned panel ventilation filters & changed sample in-line filter. Checked functional operation of fans with simulated alarm using calibration test gas. Re-set maintenance timer - LC																				
<b>Result: Pass</b>																				
Remedial Required? No																				
<b>Completed By:</b>			<b>Name:</b>																	
Liam Colbert																				
<b>Signature:</b>			<b>Signature:</b>																	
																				
<b>Next Visit Due:</b>		<b>Service Interval:</b>	<b>Date:</b>																	
04-Nov-17		6	04-May-17																	

For Office Use Only: Landline St. Ambrose Glasgow

01-Apr-18

Send To: Gerry Boyle boyleg@northlan.gov.uk