## SAFETYGASDETECTION

## SERVICE RECORD

## **Using Technology to Safeguard Life**

Customer	North Lanarkshire Counsil		Postcode	ML2 2HT Townhead Rd			
Building	Main School Building		Room	Janitors Office			
Contact	Ellen Douglas (H	lead) / Helen Taylor					
Manufacturer	SGD		S/N	120203-002			
Sys Description	Inteligent Fan Co	ontrol System					
Notes	Normal Panel Key.						
Gas Measured	CH4%	CO2%			Sensor List:		
1st Alarm Level	1.0	1.0			No. Type	Date Due	Qty
2nd Alarm Level	2.5	2.5			Pump, Double Head	23-May- 19	1
3rd Alarm Level					CO2-Dyn		1
4th Alarm Level Task:					CH4-Dyn CH4-Dyn		1
Calibration Functional Test Changed Sensors #:2  Test Gas: #1062 : 250ppm CO /  Notes: Call Out ans Service. Sensor no.2 (CO2 in I Changed no.2 & reset	2% CO2 / 2.5% C	H4 / 15% O2 / 80.5% N2 % on arrival)			NSD23/05/2019		
Remedial Required? Fit 5% range CO2 ser  Completed By:	Yes	but Requi	Name:	dial			
Signature: Next Visit Due: 1	0-May-19	Service Interva		10-Oct-18			

For Office Use Only: St. Ambrose Glasgow North Lanarkshire School

01-May-19

Send To: Gerry Boyle boyleg@northlan.gov.uk